

Lowell and  
Teresa Norbom  
33783 TC Rd.

**WELLS**

Mick  
Newton  
33660 TC Rd.

**Norboms lost their well because earth movement destroyed their well casing. They had to drill their new well right next to their ruined well because there is no where else on the bluff that they live on that they can get a drill rig on.**


**The Newton Residence has had his water feed line from well head to house pulled apart 3 times and his house and surrounding concrete separate by several inches. All from earth movement.**

**Increased traffic and any heavy traffic could be disastrous to all their health safety and well being . Not to speak of their property values.**

**Petersen Rock Pits.  
Deep holes with  
vertical walls**

Something is seriously going on under ground here that cannot be denied nor ignored

**A TIA inclusive of a Geohydrologist and Geotechnical monitoring specifically aimed at Tide Creek Road and the homes and issues of 33783 and 33660 located on Tide Creek Rd. should be done now that all are aware of these easily documentable issues.**



Lowell and  
Teresa Norbom  
33783 TC Rd.

**BIG WELL  
ISSUES**

Mick  
Newton  
33660 TC Rd.

**BIG WELL  
ISSUES**

Where Century Link  
Fiber Optic Cable was  
pulled apart by earth  
movement recently  
and had to be dug up  
and spliced together

There have been slides  
on both Tide creek Road  
and Hwy 30

**Petersen Rock Pits.  
Deep holes with  
vertical walls**

Tide Creek  
Aggregate, LLC

Rock Quarry Rd

**Extremely Dangerous Driveways**

Lowell and Teresa Norbom  
33783 TC Rd.

Mick Newton  
33660 TC Rd.

**Yellow ARROWS is very steep ground**

**Dips and heave areas in Hwy. 30 they keep fixing**

These are all just gravel rds. in rock pit area

**Petersen Rock Pits. Deep holes with vertical walls**

Tide Creek Aggregate, LLC

Rock Quarry Rd

