



JOHN GUMM BUILDING PROJECT UPDATE

Columbia County, OR

DEMOLITION, FOUNDATION AND STRUCTURAL UNDERWAY!

Over the last month, we have been resolving several structural components in the building as we construct a solid foundation for the building going forward. We have built and filled in the mezzanine area around the auditorium. This has really opened the second floor and created so much space for future use. We have replaced rotted wood structures in the basement that were uncovered during demolition and poured concrete slab. WE are prepping to pour a new retaining wall to support the structure for years to come. John Gumm is resting on a sure foundation going forward.

WHAT'S NEXT

Demolition will continue and framing will begin next. Electrical pathways will start to go in and equipment will start to be delivered. The new retaining wall will be poured and go in next month.



Level 2 Mezzanine Floor Infill



Rebar at Retaining Wall Roofing



Basement Pony Wall Framing and Concrete